

TABLE OF CONTENTS

Alphabetical List of XPS Spectra in Volume Four (based on Chemical Abbreviations)	v
Introduction	viii
Organization and Details of Spectral Sets	ix
A. Organization of Spectra.....	ix
B. Contents of Each Set of Spectra.....	ix
C. Philosophy of Data Collection Methods	x
D. Peak-Fitting (Curve-Fitting) of High Energy Resolution Spectra	x
E. Charge Compensation of Insulating Materials.....	xi
F. Abbreviations Used.....	xi
Instrument and Analysis Details used to make Spectral Data..	xii
A. Instrument Details	xii
B. Experimental Details	xiii
C. Data Processing Details	xiv
D. Sample Details.....	xiv
Sources of Elements and Chemical Compounds	xiv
Source of Polymer Materials.....	xv
Source of Alloys	xv
Source of Semi-Conductor Materials.....	xv
Sources of Commercially Pure Binary Oxides	xv
Powdered Samples Pressed into 3 mm Diameter Pellets.....	xv
Benefits of Pressing Powders into Pellets (increased count rate and simple charge control)	xvi
Problems Caused by Pressing Samples into Pellets.....	xvi
Solution to Pressure Induced Contamination of Pellets	xvi
Source of Pellet Press Equipment	xvii
E. Energy Resolution Details.....	xvii
F. Energy Scale Reference Energies and Calibration Details.	xviii
Reference Energies of Adventitious Hydrocarbon Contaminants.....	xviii
Instrument Stability and Long Term Energy Scale Calibration.	xix

G. Electron Counting and Instrument Response Function Details	xix
Instrument Response Function	xix
Signal / Background Ratios for Ion Etched Silver (Ag) using a 250 x 1000 μ X-ray Beam.....	xix
Lens Voltage Settings Available via Software under Instrument Calibration Routines	xx
H. Effects of Poorly Focusing the Distance between the Sample and the Electron Collection Lens	xx
I. Quantitation Details and Choice of "Sensitivity Exponent"	xx
J. Crude Tests of the Reliability of Scofield Based Relative Sensitivity Factors.....	xxi
K. Traceability Details.....	xxi
Traceability of Reference Binding Energies (Calibration)	xxi
Traceability Transfer from Pure Metals to Non-Conductive Binary Oxides	xxii
Traceability of Relative Sensitivity Factors used for Quantitation.....	xxii
Traceability of Sample Purity	xxii
L. Reference Papers Describing the Capabilities of X-Probe, M-Probe, and S-Probe XPS Systems	xxiii
M. Spectra of Polymers & Polymers Damaged by X-rays	
(atom % tables, wide scan survey, high energy resolution, valence band, and other essential spectra)	xxiv
N. Alphabetical INDEX of XPS Spectra in Volume Four (based on Chemical Abbreviations)	APPENDIX "A"