

TABLE OF CONTENTS

Alphabetical List of XPS Spectra in Volume Five (based on Chemical Abbreviations)	v
Introduction	ix
Organization and Details of Spectral Sets	x
A. Organization of Spectra	x
B. Contents of Each Set of Spectra	x
C. Philosophy of Data Collection Methods	xi
D. Peak-Fitting (Curve-Fitting) of High Energy Resolution Spectra	xi
E. Charge Compensation of Insulating Materials	xii
F. Abbreviations Used	xii
Instrument and Analysis Details used to make Spectral Data	xiii
A. Instrument Details	xiii
B. Experimental Details	xiv
C. Data Processing Details	xv
D. Sample Details	xv
Sources of Elements and Chemical Compounds	xv
Source of Polymer Materials	xvi
Source of Alloys	xvi
Source of Semi-Conductor Materials	xvi
Sources of Commercially Pure Binary Oxides	xvi
Powdered Samples Pressed into 3 mm Diameter Pellets	xvi
Benefits of Pressing Powders into Pellets (increased count rate and simple charge control)	xvii
Problems Caused by Pressing Samples into Pellets	xvii
Solution to Pressure Induced Contamination of Pellets	xvii
Source of Pellet Press Equipment	xviii
E. Energy Resolution Details	xviii
F. Energy Scale Reference Energies and Calibration Details	xix
Reference Energies of Adventitious Hydrocarbon Contaminants	xix
Instrument Stability and Long Term Energy Scale Calibration	xx

G. Electron Counting and Instrument Response Function Details	xx
Instrument Response Function	xx
Signal / Background Ratios for Ion Etched Silver (Ag) using a 250 x 1000 μ X-ray Beam.....	xx
Lens Voltage Settings Available via Software under Instrument Calibration Routines	xxi
H. Effects of Poorly Focusing the Distance between the Sample and the Electron Collection Lens.....	xxi
I. Quantitation Details and Choice of "Sensitivity Exponent"	xxi
J. Crude Tests of the Reliability of Scofield Based Relative Sensitivity Factors.....	xxii
K. Traceability Details.....	xxii
Traceability of Reference Binding Energies (Calibration)	xxii
Traceability Transfer from Pure Metals to Non-Conductive Binary Oxides.....	xxiii
Traceability of Relative Sensitivity Factors used for Quantitation.....	xxiii
Traceability of Sample Purity.....	xxiii
L. Reference Papers Describing the Capabilities of X-Probe, M-Probe, and S-Probe XPS Systems	xxiv
M. Spectra of Rare Earth Oxides, Hydroxides, Carbonates, Nitrides, Sulfides, Carbides, Borides, Acetates, and Misc Materials (atom % tables, wide scan survey, high energy resolution, valence band, and other essential spectra)	xxv
N. Alphabetical INDEX of XPS Spectra in Volume Five (based on Chemical Abbreviations)	APPENDIX "A"