

TABLE OF CONTENTS

Alphabetical List of XPS Spectra in Volume One (based on Chemical Abbreviations)	v
Introduction	x
Organization and Details of Spectral Sets	xi
A. Organization of Spectra	xi
B. Contents of Each Set of Spectra	xi
C. Philosophy of Data Collection Methods.....	xii
D. Peak-Fitting (Curve-Fitting) of High Energy Resolution Spectra	xii
E. Charge Compensation of Insulating Materials	xiii
F. Abbreviations Used	xiii
Instrument and Analysis Details used to make Spectral Data	xiv
A. Instrument Details	xiv
B. Experimental Details.	xv
C. Data Processing Details	xvi
D. Sample Details	xvi
Sources of Elements and Chemical Compounds	xvi
Source of Polymer Materials.....	xvii
Source of Alloys.	xvii
Source of Semi-Conductor Materials.....	xvii
Sources of Commercially Pure Binary Oxides	xvii
Powdered Samples Pressed into 3 mm Diameter Pellets.....	xvii
Benefits of Pressing Powders into Pellets (increased count rate and simple charge control).....	xviii
Problems Caused by Pressing Samples into Pellets.....	xviii

TABLE OF CONTENTS

Alphabetical List of XPS Spectra by Chemical Formula (AgO to ZrO₂)	7
Introduction	11
Organization and Details of Spectral Sets	11
A. Organization of Spectra	11
B. Contents of Each Set of Spectra.....	11
C. Philosophy of Data Collection Methods	12
D. Peak-Fitting (Curve-Fitting) High Energy Resolution Spectra	13
E. Charge Compensation of Non-conductive Materials	13
F. Abbreviations Used	14
Instrument and Analysis Conditions used to Collect Spectral Data	15
A. Instrument Details.....	15
B. Experimental Details.....	16
C. Data Processing Details	17
D. Sample Details	17
Sources of Commercially Pure Binary Oxides.....	17
Powdered Samples - Pressed into 3 mm Diameter Pellets	18
Benefits of Pressing Powders into Pellets	18
Problems Caused by Pressing Samples into Pellets	19
Solution to Pressure Induced Contamination of Pellets	19
E. Energy Resolution Details	20
F. Energy Scale Reference Energies and Calibration Details	21
Reference Energies of Adventitious Hydrocarbon Contaminants	22
Instrument Stability and Long Term Energy Scale Calibration.....	22
G. Electron Counting and Instrument Response Function Details	23
Instrument Response Function	23
Signal / Background Ratios for Ion Etched Silver (Ag) using a 250 x 1000 μ X-ray Beam.....	23
Lens Voltage Settings Available via Software under Instrument Calibration Routines	23
H. Effects of Poorly Focusing the Distance between the Sample and the Electron Collection Lens	24
I. Quantization Details and Choice of "Sensitivity Exponent"	24
J. Tests of the Reliability of Scofield Based Relative Sensitivity Factors	25
K. Traceability Details	25
Traceability of Reference Binding Energies (Calibration)	25

Transfer of Traceability from Pure Metals to Non-Conductive Binary Oxides.....	26
Traceability of Instrument Response (Throughput) Function.....	26
Traceability of Relative Sensitivity Factors (RSFs) used for Quantization.....	27
Traceability of Sample Purity	27
L. Reference Papers Describing the Capabilities of S-Probe XPS Systems.....	27
M. Title Page of Section Containing Monochromatic XPS Spectra	28
N. Appendices.....	838
Charge Control Physics without Mesh and with Mesh.....	842
Table 1. Categorical List of Materials in XI Library of Monochromatic XPS Spectra.....	845
Table 2. Alphabetical List of Materials in XI Library of Monochromatic XPS Spectra.....	930
Table 3. Contamination Caused by Gloves	950
Table 4. Unknown BE Lookup Table.....	952
O. Alphabetical Index of XPS Spectra by Chemical Formula (AgO to ZrO ₂)	956

TABLE OF CONTENTS

Alphabetical List of XPS Spectra in Volume Three (based on Chemical Abbreviations)	v
Introduction	viii
Organization and Details of Spectral Sets	x
A. Organization of Spectra.....	x
B. Contents of Each Set of Spectra.....	x
C. Philosophy of Data Collection Methods.....	xi
D. Peak-Fitting (Curve-Fitting) of High Energy Resolution Spectra.....	xi
E. Charge Compensation of Insulating Materials.....	xii
F. Abbreviations Used.....	xii
Instrument and Analysis Details used to make Spectral Data	xiii
A. Instrument Details.....	xiii
B. Experimental Details.....	xiv
C. Data Processing Details.....	xv
D. Sample Details.....	xv
Sources of Elements and Chemical Compounds.....	xv
Source of Polymer Materials.....	xvi
Source of Alloys.....	xvi
Source of Semi-Conductor Materials.....	xvi
Sources of Commercially Pure Binary Oxides.....	xvi
Powdered Samples Pressed into 3 mm Diameter Pellets.....	xvi
Benefits of Pressing Powders into Pellets (increased count rate and simple charge control).....	xvii
Problems Caused by Pressing Samples into Pellets.....	xvii
Solution to Pressure Induced Contamination of Pellets.....	xvii
Source of Pellet Press Equipment.....	xviii
E. Energy Resolution Details.....	xviii
F. Energy Scale Reference Energies and Calibration Details.....	xix
Reference Energies of Adventitious Hydrocarbon Contaminants.....	xix
Instrument Stability and Long Term Energy Scale Calibration.....	xx

G. Electron Counting and Instrument Response Function Details	xx
Instrument Response Function	xx
Signal / Background Ratios for Ion Etched Silver (Ag) using a 250 x 1000 μ X-ray Beam	xx
Lens Voltage Settings Available via Software under Instrument Calibration Routines	xxi
H. Effects of Poorly Focusing the Distance between the Sample and the Electron Collection Lens	xxi
I. Quantitation Details and Choice of "Sensitivity Exponent"	xxi
J. Crude Tests of the Reliability of Scofield Based Relative Sensitivity Factors	xxii
K. Traceability Details	xxii
Traceability of Reference Binding Energies (Calibration)	xxii
Traceability Transfer from Pure Metals to Non-Conductive Binary Oxides	xxiii
Traceability of Relative Sensitivity Factors used for Quantitation	xxiii
Traceability of Sample Purity	xxiii
L. Reference Papers Describing the Capabilities of X-Probe, M-Probe, and S-Probe XPS Systems	xxiv
M. Spectra of Semiconductors	
(atom % tables, wide scan survey, high energy resolution, valence band, and other essential spectra)	xxv
N. Alphabetical INDEX of XPS Spectra in Volume Three (based on Chemical Abbreviations)	APPENDIX "A"

TABLE OF CONTENTS

Alphabetical List of XPS Spectra in Volume Four (based on Chemical Abbreviations)	v
Introduction	viii
Organization and Details of Spectral Sets	ix
A. Organization of Spectra.....	ix
B. Contents of Each Set of Spectra.....	ix
C. Philosophy of Data Collection Methods	x
D. Peak-Fitting (Curve-Fitting) of High Energy Resolution Spectra	x
E. Charge Compensation of Insulating Materials.....	xi
F. Abbreviations Used.....	xi
Instrument and Analysis Details used to make Spectral Data..	xii
A. Instrument Details	xii
B. Experimental Details	xiii
C. Data Processing Details	xiv
D. Sample Details.....	xiv
Sources of Elements and Chemical Compounds	xiv
Source of Polymer Materials.....	xv
Source of Alloys	xv
Source of Semi-Conductor Materials.....	xv
Sources of Commercially Pure Binary Oxides	xv
Powdered Samples Pressed into 3 mm Diameter Pellets.....	xv
Benefits of Pressing Powders into Pellets (increased count rate and simple charge control)	xvi
Problems Caused by Pressing Samples into Pellets.....	xvi
Solution to Pressure Induced Contamination of Pellets	xvi
Source of Pellet Press Equipment	xvii
E. Energy Resolution Details.....	xvii
F. Energy Scale Reference Energies and Calibration Details.	xviii
Reference Energies of Adventitious Hydrocarbon Contaminants.....	xviii
Instrument Stability and Long Term Energy Scale Calibration.	xix

G. Electron Counting and Instrument Response Function Details	xix
Instrument Response Function	xix
Signal / Background Ratios for Ion Etched Silver (Ag) using a 250 x 1000 μ X-ray Beam.....	xix
Lens Voltage Settings Available via Software under Instrument Calibration Routines	xx
H. Effects of Poorly Focusing the Distance between the Sample and the Electron Collection Lens	xx
I. Quantitation Details and Choice of "Sensitivity Exponent"	xx
J. Crude Tests of the Reliability of Scofield Based Relative Sensitivity Factors.....	xxi
K. Traceability Details.....	xxi
Traceability of Reference Binding Energies (Calibration)	xxi
Traceability Transfer from Pure Metals to Non-Conductive Binary Oxides	xxii
Traceability of Relative Sensitivity Factors used for Quantitation.....	xxii
Traceability of Sample Purity	xxii
L. Reference Papers Describing the Capabilities of X-Probe, M-Probe, and S-Probe XPS Systems	xxiii
M. Spectra of Polymers & Polymers Damaged by X-rays	
(atom % tables, wide scan survey, high energy resolution, valence band, and other essential spectra)	xxiv
N. Alphabetical INDEX of XPS Spectra in Volume Four (based on Chemical Abbreviations)	APPENDIX "A"

TABLE OF CONTENTS

Alphabetical List of XPS Spectra in Volume Five (based on Chemical Abbreviations)	v
Introduction	ix
Organization and Details of Spectral Sets	x
A. Organization of Spectra	x
B. Contents of Each Set of Spectra	x
C. Philosophy of Data Collection Methods.....	xi
D. Peak-Fitting (Curve-Fitting) of High Energy Resolution Spectra.....	xi
E. Charge Compensation of Insulating Materials	xii
F. Abbreviations Used	xii
Instrument and Analysis Details used to make Spectral Data	xiii
A. Instrument Details	xiii
B. Experimental Details	xiv
C. Data Processing Details	xv
D. Sample Details.....	xv
Sources of Elements and Chemical Compounds	xv
Source of Polymer Materials	xvi
Source of Alloys	xvi
Source of Semi-Conductor Materials	xvi
Sources of Commercially Pure Binary Oxides.....	xvi
Powdered Samples Pressed into 3 mm Diameter Pellets.....	xvi
Benefits of Pressing Powders into Pellets (increased count rate and simple charge control).....	xvii
Problems Caused by Pressing Samples into Pellets	xvii
Solution to Pressure Induced Contamination of Pellets.....	xvii
Source of Pellet Press Equipment.....	xviii
E. Energy Resolution Details.....	xviii
F. Energy Scale Reference Energies and Calibration Details.....	xix
Reference Energies of Adventitious Hydrocarbon Contaminants	xix
Instrument Stability and Long Term Energy Scale Calibration.....	xx

G. Electron Counting and Instrument Response Function Details	xx
Instrument Response Function	xx
Signal / Background Ratios for Ion Etched Silver (Ag) using a 250 x 1000 μ X-ray Beam.....	xx
Lens Voltage Settings Available via Software under Instrument Calibration Routines	xxi
H. Effects of Poorly Focusing the Distance between the Sample and the Electron Collection Lens.....	xxi
I. Quantitation Details and Choice of "Sensitivity Exponent"	xxi
J. Crude Tests of the Reliability of Scofield Based Relative Sensitivity Factors.....	xxii
K. Traceability Details.....	xxii
Traceability of Reference Binding Energies (Calibration)	xxii
Traceability Transfer from Pure Metals to Non-Conductive Binary Oxides.....	xxiii
Traceability of Relative Sensitivity Factors used for Quantitation.....	xxiii
Traceability of Sample Purity.....	xxiii
L. Reference Papers Describing the Capabilities of X-Probe, M-Probe, and S-Probe XPS Systems	xxiv
M. Spectra of Rare Earth Oxides, Hydroxides, Carbonates, Nitrides, Sulfides, Carbides, Borides, Acetates, and Misc Materials (atom % tables, wide scan survey, high energy resolution, valence band, and other essential spectra)	xxv
N. Alphabetical INDEX of XPS Spectra in Volume Five (based on Chemical Abbreviations)	APPENDIX "A"